

Oil Field Environmental Incident Summary

Incident: 20140114133008 **Date/Time of Notice:** 01/14/2014 12:38

Responsible Party: Deer Valley Trucking

Well Operator: STATOIL OIL & GAS LP

Well Name: BORSHEIM TRUST 33-28 #3H

Field Name: TODD

Well File #: 21709

Date Incident: 1/14/2014 **Time Incident:** 0203

Facility ID Number:

County: WILLIAMS

Twp: 155

Rng: 101

Sec: 28

Qtr:

Location Description: Off county road slightly just down from well locations. 48 1336.05 - 103 4115.40

Submitted By: Robert Cude

Received By:

Contact Person: Robert Cude
6300 BRIDGE POINT PKY, BLDG 2
SUITE 500
AUSTIN, TX 78730

General Land Use: Other - Described Above

Affected Medium: Topsoil

Distance Nearest Occupied Building: 0.3 Miles

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	1.7	barrels	1.7	barrels	1.7	barrels
Brine	0	barrels	0	barrels		
Other	0	barrels	0	barrels		

Description of Other Released Contaminant:

Tanker roll-over in to borrow pit when exiting well pad.

Inspected:

Written Report Received: 9/1/2016

Clean Up Concluded: 1/22/2014

Risk Evaluation:

None

Areal Extent:

10 x 50

Potential Environmental Impacts:

Soil if contaminated will be removed, stored and tested for disposal. At present there is no soil penetration only snow has been effected.

Action Taken or Planned:

Oil was contained by tanker position. Immediate action was taken and berms created to stop any potential additional spread when tanker was rolled back over. No leakage occurred during recovery of tanker.

Wastes Disposal Location: Nuverra Environmental Treatment Center

Agencies Involved: Local Law Enforcement

Updates

Date: 1/15/2014 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release due to truck accident, just off the well pad, in a borrow pit. Followup is necessary.

Date: 1/22/2014 **Status:** Inspection

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

1/22/2014 at 13:56, on location. Borrow pit has been scraped, no stain observed within scraped pit or culvert within pit. Ground under a disposal container by pit has noticeable staining, called contact and notified them of need to clean ground by container as well. According to contact container is holding material from spill in pit. Will need to check area again in a few weeks to confirm ground has been cleaned.

Date: 7/9/2014 **Status:** Inspection

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

7/9/2014 at 12:35, on location. Area scraped in ditch now revegetated. Area where rolloff was located has no visible staining on the ground.